

Section 2

Brushes



Part Number / Description	Part Image / Technical Drawing
<p data-bbox="245 656 419 689">MDOO2.32</p> <p data-bbox="140 732 528 804">Outer Lower Rubber Flap Kit</p>	 A photograph of the Outer Lower Rubber Flap Kit (MDOO2.32). It consists of a black cylindrical rubber flap and a long, thin black metal strip with a hole at one end. A watermark for Carlyle Bus & Coach Limited is visible over the image.
<p data-bbox="245 1160 419 1193">MDOO2.33</p> <p data-bbox="148 1236 520 1308">Bottom Rubber Draught Band</p>	 A photograph of the Bottom Rubber Draught Band (MDOO2.33). It is a thick, dark grey rubber band with a hole at one end. A watermark for Carlyle Bus & Coach Limited is visible over the image.

Section 2.3

West Bromwich
0121 524 1200

Bristol
0117 955 4955

Glasgow
0141 429 2704

London
01932 349 396

Manchester
0161 457 9800

Dublin
00353 1899 1060